



April 16, 2010

To whom it may concern.

CMA Corporation Limited is a leading integrated recycling group that provides products and services to customers across three continents. The group's major activities are the processing and recycling of predominantly secondary ferrous and non-ferrous metal products. CMA employs a variety of advanced high-end recycling technologies to add value and open new markets for the group.

One of our key pieces of equipment in our Tauranga facility is our Lindeman Mosley Shear Baler.

In October 2009 we completed a routine hydraulic oil change. After a few days we noticed we had a problem. We sampled the oil and the result was we had a .0581% water contamination in the 2400 Litre system and an oil evaluation code of 'C'

Having only just replaced the oil we sought an alternative to an expensive draining and flushing the entire hydraulic system.

We were referred to Global Oil Solutions NZ Ltd by another business who thought that the Kleenoil system might be able to help due to its ability to remove both low micron contaminants and water out of the oil during regular operation.

After seeing the Kleenoil system I was very sceptical that it would work. However after a couple of filter changes using the Kleenoil system, the entire system Went from milky white back to golden; new oil. We took another sample of the hydraulic oil and the oil lab results came back as good for continued use.

We have now installed a Kleenoil system on our other bailer on site and would recommend to anyone wanting to protect their oil from contamination to install a Kleenoil system.

Sincerely,

Peter

A handwritten signature in black ink, appearing to read "Peter Mitchell". Below the signature, the name "Peter Mitchell" is written in a cursive script, followed by "company Engineer." in a similar cursive script.

Peter Mitchell
company Engineer.